

HYDROMETERS ACC. TO BAUMÉ

TECHNICAL DATA, PRODUCT VERSIONS AND ACCESSORIES



The following table lists the various features of hydrometers acc. to Baumé , including the measuring range, resolution, accuracy, types and the accessories as well as the associated data.

FEATURE	VARIANTS
Measuring range	0 to 75 °Bé
Resolution	Up to 0,1 °Bé
Accuracy	±0.1 °Bé
Reference temperature	+15 °C +20 °C
Types	Range finders Hydrometers acc. to Baumé
Accessories	Cylindrical stands made of glass